



INSTALLATION GUIDELINE

Purpose: To prevent electrical shock, maintain required safety creepage and clearance between power supply and nearby components.

Scope: This application note is applicable for open-frame power supply.

Guidelines:

Mounting holes which are on primary or input side and not connected to earth should have non-metallic mounting stud or spacer for isolation.

Below is snapshot of Nylon spacer which can be mounted in end chassis with screw. This spacer has flexible locking mechanism on top, which can be inserted into PSU mounting hole by slight pressing.

Vendor and vendor part nos. are provided for reference only.

Vendor: Pingood enterprise co. ltd.

P/N: BCMS-6

